

DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

1594 West North Temple, Suite 1210 PO Box 145801 Salt L

801-5 801-3 801-5

IN

| SPECTION REPORT | λ | Ship S |
|-----------------------|-----------|--------|
| ete: XXX Exploration: | | β' |

| Governor | |
|---------------------------------------|--|
| Kathleen Clarke Executive Director | |
| Lowell P. Braxton | |

Michael O. Leavitt

| ake City, Utah 84114-5801 | Partial: Complete: XXX Exploration: |
|----------------------------|---|
| i38-5340 i59-3940 (Fax) | Inspection Date & Time: 09/10&18/2001 / 10:00-14:00 |
| 38-7223 (TDD) | Date of Last Inspection: 08/06/2001 |

| Mine Name: <u>Deer Creek Mine</u> County: <u>Emery</u> | Permit Number: <u>C/015/018</u> |
|---|---------------------------------------|
| Permittee and/or Operator's Name: PacifiCorp | |
| Business Address: P.O. Box 310, Huntington, Utah 84528 | |
| Type of Mining Activity: Underground XXX Surface _ | Prep. Plant Other |
| Company Official(s): <u>Dennis Oakley</u> | _ |
| State Official(s): Stephen J. Demczak, Karl R. Houskeeper | Federal Official(s): None |
| Weather Conditions: Partly Cloudy 70's | · · · · · · · · · · · · · · · · · · · |
| Existing Acreage: Permitted 18,866 Disturbed 95.79 F | Regraded Seeded |
| Status: Active XXX | |

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

| | | EVALUATED | <u>N/A</u> | COMMENTS | NOV/ENF |
|-----|---|------------------|------------|-----------------|---------|
| 1. | PERMITS, CHANGE, TRANSFER, RENEWAL, SALE | [X] | \Box | [X] | \Box |
| 2. | SIGNS AND MARKERS | [X] | \Box | [X] | \Box |
| 3. | TOPSOIL | [X] | П | [X] | \Box |
| 4. | HYDROLOGIC BALANCE: | | | | |
| | a. DIVERSIONS | [X] | \Box | [X] | \Box |
| | b. SEDIMENT PONDS AND IMPOUNDMENTS | [X] | \Box | [X] | П |
| | c. OTHER SEDIMENT CONTROL MEASURES | [X] | \Box | [X] | Ц |
| | d. WATER MONITORING | [X] | П | [X] | Ц |
| | e. EFFLUENT LIMITATIONS | [X] | П | П | Ц |
| 5. | EXPLOSIVES | [X] | П | | П |
| 6. | DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES | [X] | П | Ц | |
| 7. | COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS | [X] | П | [X] | П |
| 8. | NONCOAL WASTE | [X] | П | [X] | \Box |
| 9. | PROTECTION OF FISH, WILDLIFE AND RELATED | | | | |
| | ENVIRONMENTAL ISSUES | [X] | П | П | Ш |
| | SLIDES AND OTHER DAMAGE | [X] | \Box | Ц | |
| 11. | CONTEMPORANEOUS RECLAMATION | [X] | \Box | Ц | \Box |
| 12. | BACKFILLING AND GRADING | [X] | П | Ц | П |
| 13. | REVEGETATION | [X] | \Box | ∐. | П |
| | SUBSIDENCE CONTROL | [X] | Ц | [X] | П |
| 15. | CESSATION OF OPERATIONS | [X] | \Box | П | |
| 16. | ROADS: | _ | | r. 2 | |
| | a. CONSTRUCTION/MAINTENANCE/SURFACING | [X] | П | Ц | Ц |
| | b. DRAINAGE CONTROLS | [X] | Ц | Ц | П |
| | OTHER TRANSPORTATION FACILITIES | [X] | Ц | | Ц |
| | SUPPORT FACILITIES/UTILITY INSTALLATIONS | [X] | Ц | [X] | П |
| | AVS CHECK (4th Quarter- April, May, June) | [X] | П | Ц | П |
| | AIR QUALITY PERMIT | [X] | Ц | [X] | Ц |
| 21. | BONDING & INSURANCE | [X] | \Box | [X] | |

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: C/015/018

DATE OF INSPECTION: 09/10&18/2001

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

GENERAL COMMENTS

Conducted a complete inspection of the Deer Creek Mine on September 10 & 18, 2001. The paper work was reviewed September 10, 2001 and a field inspection was done September 18, 2001.

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

- -The DOGM permit expires 02/07/2006.
- -Certificate of Insurance Policy # U0614A00 terminates 04/01/2002. Coverage is by Assoc. Elec. & Gas Ins. SVSC LTD.
- -Reclamation agreement is dated December 11, 2000. The bonding amount is \$3,000,000. The operator's copy of the reclamation agreement is not signed by the Division, only by the Operator. Told the Operator that they need to request a signed copy from the Division and keep it on file.
- -UPDES permit UT0023604 expires 11/30/2002.
- -Air quality permit NO. DAQE-926-96 issued 10/04/1996 allows for 4,500,000 tons per 12 month period. A second permit is for the waste rock site DAQE-926-91.

2. SIGNS AND MARKERS

The ID sign is in place. Other markers, as required by the coal rules, are in place.

3. TOPSOIL

The topsoil pile was spot-checked with no signs of erosion.

4A. HYDROLOGIC BALANCE: DIVERSIONS

Several diversions were spot-checked and complied with the R645 Coal Rules. No water was flowing during the inspection.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The mine site's sediment pond was inspected with no hazardous conditions noticed. The pond was discharging during the inspection.

The mine site pond was inspected June 29, 2001 and the waste rock site was inspected June 18, 2001.

4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

Sediment control measures along the belt line were inspected and it appeared they would function if an event occurred. The road and berm were graded along the belt line.

4D. HYDROLOGIC BALANCE: WATER MONITORING

The first quarter water monitoring report was reviewed at the mine office.

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: C/015/018

DATE OF INSPECTION: <u>09/10&18/2001</u>

The permittee has submitted the water monitoring data for first quarter into the Electronic Water Database. The second quarter water monitoring data has not been submitted into the Electronic Water Database, but is in process. The permittee said the information will be entered by the end of the third quarter. The third quarter water samples are being taken at this time. The permittee said the samples will be taken by the end of the third quarter.

7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

The refuse piles were inspected by the permittee for second quarter and the report was P.E. certified. The Waste Rock Disposal Site and Elk Canyon were inspected on June 18, 2001.

8. NONCOAL WASTE

The mine site had some noncoal waste that had been blown from the containment area. The material was being picked up during the inspection.

14. SUBSIDENCE CONTROL

The permittee will be submitting the subsidence information in the Annual Report.

18. SUPPORT FACILITIES/UTILITY INSTALLATIONS

The permittee has built a concrete pad at Rilda Canyon to aid in the unloading of longwall shields.

20. AIR QUALITY PERMIT

The permittee has two Air Quality Permits for Deer Creek Mine: 1) waste rock site DAQE-926-91 and, 2) preparation plant DAQE-926-96. The preparation plant is permitted to process 4.5 million tons per year.

21. BONDING AND INSURANCE

Certificate of Insurance Policy # U0614A00 terminates 04/01/2002. The acord form was inspected and complied with the R645 Coal Rules.

Reclamation agreement is dated December 11, 2000. The bonding amount is \$3,000,000. The operator's copy of the reclamation agreement is not signed by the Division, only by the Operator. Told the Operator that they need to request a signed copy from the Division and keep it on file.

Inspector's Signature:

Karl R. Houskeeper

Date: September 19, 2001

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM

Chuck Semborski, PacifiCorp

Price Field office

O:\015018.DER\Compliance\2001\c_0918.wpd